Beaver Lake Middle School - Change Order #7 - Kuper/Mullins

Action to be taken:

I move the board approve the Beaver Lake Middle School Change Order #7 from Cornerstone General Contractors in the amount of \$111,590.06 plus \$11,270.59 WSST for a total of \$122,860.65

Each proposal request listed on the attached Change Order No. 7 has been reviewed by the District Construction Coordinator for the project. Cost proposals were reviewed and reduced where possible and as proposed represent an equitable charge for the scope of work involved.

•	PCO-020	Additional costs related to revisions to the painting, wall covering and art rails in the Commons and corridors caused by existing conditions of the existing wall coverings.
•	PCO-047	Additional costs related to the upgrade of the stain on the MDF wall panels.
•	PCO-049	Additional costs related to overtime on New Year's Eve due to lost time related to inclement weather and road conditions.
•	PCO-050	Additional costs related to additional door security contacts not included in original contract.
•	PCO-056	Additional costs related to overtime and swing-shift work caused by supply chain delays in HVAC equipment.
•	PCO-057	Additional costs related to wall panel revisions for existing wall conditions.
•	PCO-061	Additional costs related to the wiring of the fire alarm system at the covered play area.
•	PCO-062	Additional costs related to the unit reconfiguration and ducting at HVAC unit 1-02.
•	PCO-063	Additional costs related to cost premiums of concrete due to concrete/teamster's strike.
•	PCO-064	Additional costs related to the removal of the existing roller shade and add of a new at the Music Office.
•	PCO-065	Additional costs related to coordination of wiring, casework and existing conditions.
•	PCO-066	Additional costs related to removal of existing and addition of new wall coverings.
•	PCO-067	Additional costs related to the tie-in between the new Music Addition and the existing building.
•	PCO-068	Additional costs related to removal of existing wall coverings, prep and paint.
•	PCO-069	Additional costs related to patching and painting in the Staff Lounge due to MEP revisions.
•	PCO-070	Additional costs related to welding new baseplates on existing bike racks so they could be relocated.
•	PCO-071	Additional costs related to removal ceiling mounted projector brackets, patch and replace ceiling tiles.
•	PCO-072	Additional costs related to the demo of existing and replacement with new concrete bench at west stair.

Revised Contract Total	\$5,601,812.08
Total Change Order #7	\$122,860.65
10.1% WSST	\$11,270.59
Change Order # 7	\$111,590.06
Previous Contract Total including change orders and WSST	\$5,478,951.43
Original Contract Total including WSST	\$5,011,752.00
Original Contract Sum (without WSST)	\$4,552,000.00

The revised contract total is within the project budget.

Jake Kuper or Tom Mullins will be available to answer any questions the board may have regarding this recommendation.

Please scroll down to view Beaver Lake Middle School Change Order 7 (2 pages).

CHANGE ORDER							
CHANGE OR	RDER NO. 07 PROJECT Beaver Lake Middle School						
	OF 2 DATE ISSUED February 24, 2021 ARCHITECT'S PROJECT NO2						
	ornerstone General Contractors						
	re by Owner and Architect you are directed to make the following changes in your Contract dated May 21, 2021 with						
	Issaquah School District No. 411 (OWNER) for the a	bove referenced project					
The Contrac	ct is changed as follows:						
PCO-020	CCD-016 Painting – Commons & Corridor	\$12,606.20					
1.							
PCO-047	MDF Panel Finish	\$ 8,661.14					
1.	ADDED Costs associated with upgrading and refinishing stain on MDF wainscot panels.						
PCO-049	Overtime on New Year's Eve	\$ 2,528.48					
1.	ADDED costs associated with overtime worked on New Year's Eve to make up for a lost schedule day due and road conditions. The extra day was necessary in order to maintain schedule during winter break.	to inclement weather					
PCO-050 1.	Band Room Storage Area Security ADDED costs associated with adding door contacts to new exterior doors at both music rooms. Costs included by the cabling associated with tying these doors into the security system.	\$ 8,146.73 ide door contacts and					
PCO-056	OT and Premium Time Rates from HVAC Equipment Delays ADDED Costs associated with the overtime and swing shift premiums that were incurred from delayed equipment deliverie to unforeseen causes. Costs incurred are only to meet schedule dates and/or accommodate the district's daytime activities						
PCO-057	MDF Wainscot Conflicts ADDED costs associated with cutting wainscot around existing wall mounted devices.	\$ 4,042.10					
PCO-061 1.	Fire Alarm Wiring for Covered Play Dry System Riser ADDED costs associated with connecting fire alarm system to the covered play dry-system fire sprinkler.	\$ 1,248.06					
PCO-062	Heat Pump 1-02 Configuration ADDED Costs associated with unit reconfiguration and ducting revisions to heat pump 1-02.	\$ 5,883.13					
PCO-063 1 ₋	Instrument Storage Sidewalk Concrete Premium ADDED Costs associated with the overtime and swing shift premiums that were incurred from delayed equ to unforeseen causes. Costs incurred are only to meet schedule dates and/or accommodate the district's d						
PCO-064 1.	Roller Shade at Music Office ADDED Costs associated with removing existing roller shade and procuring and installing a new roller shade	\$ 603.48 de in the Music Office.					
PCO-065 1.	Casework and Electrical Revisions ADDED Costs associated with electrical and casework revisions necessary to coordinate existing condition casework and wall finishes.	\$ 4,327.88 as with newly installed					
PCO-066 1.	Vinyl Wallcovering Removal at Tackable Wallcovering locations ADDED Costs associated with the removal of VWC at areas to receive new tackable wallcovering Existing be removed and wall prepped before installation.	\$13,360.44 g wallcovering had to					
PCO-067 1.	Instrument Storage Flashing at Existing Building Joint ADDED Costs associated with anchoring, flashing, and finishing exterior wall surfaces where new music rewere cut into the existing exterior walls.	\$ 3,761.92 porm door openings					

CHANG	E ORDER					
CHANGE ORDER NO PROJECT Beaver Lake Middle School						
PCO-068 1.	Music Room Wallcovering and Painting ADDED Costs associated with removing existing wallcoverings, prepping, and painting wa	ılls in both music roon	\$ 9,977.31			
PCO-069 1.	Drywall Repairs for MEP Revisions ADDED Costs associated with revisions to MEP in the Staff Lounge. Patching and repairing	ng wall board.	\$ 2,310.90			
PCO-070 1.	Relocated Bike Racks ADDED Costs associated with welding new baseplates to existing, relocated bike racks.		\$ 1,798.63			
PCO-071 1.	Projector Mount Demo and Patching ADDED Costs associated with the removal of the existing ceiling-mounted classroom projected deciling cover plate.	ector mount frames. (\$ 2,479.80 Costs include			
PCO-072	West Stair Concrete Bench Demo ADDED Costs associated with demolition and forming and pouring of a portion of the concunforeseen existing conditions.	rete bench under the	\$ 3,124.73 west stairs due to			
		TOTAL	\$111,590.0 <u>6</u>			
The net cha The Contrac The Contrac The new Co The Contrac	Contract Sum nge by previously authorized Change Order ct Sum prior to this Change Order was ct Sum will be increased by this Change Order in the amount of intract Sum including this Change Order will be ct Time will be changed by Substantial Completion as of the date of this Change Order therefore is	9	\$4,552,000.00 \$29,730.71 \$4,976,341.01 \$111,590.06 \$5,087,931.07 Zero (0) days nber 30, 2021			
Architect: Contractor:	Integrus Architecture Corgerstone General Contractors	Date: 02/24/20				

Owner:

Issaquah School District

Date: _____